## Technical Bulletin

Bulletin No: TCH-29-002 Effective Date: 10/1/22 Cancels: N/A Page: 1 of 2

## Subject: Resolving Diagnostic Trouble Code (DTC) 302 on Bendix™ FLR-21™ Radar Sensors

This bulletin provides the software update to resolve Diagnostic Trouble Code (DTC) 302 on Bendix<sup>™</sup> FLR-21 Radar Sensors. This document is applicable for vehicles with FLR-21 radar sensors and Bendix<sup>™</sup> AutoVue<sup>®</sup> FLC-20<sup>™</sup> Cameras.

## BENDIX™ AUTOVUE® FLC-20™ CAMERA SOFTWARE UPDATE PROCEDURE

Diagnostic Trouble Code (DTC) 302 is seen on *newer* FLR-21 radar software which is connected to *older* FLC-20 camera software. To resolve this DTC, perform the following steps to update the software on the camera.




1. Download the FLC-20 BX193360 software update utility.








- Go to b2bendix.com.
- Select Service & Support, then Software Download.
- In the Software Type field, select Bendix FLC20 Camera.
- · Select Search.
- Locate FLC20 BX193360 (PTC 1.59) 1-Click Update Application Pack and select Download Software.
- 2. Set up the FLC20 BX193360 software update utility.
  - Extract the installation file to your desktop or download folder.



Double click the installation file and follow the installation instructions.

Bulletin No: TCH-29-002 Effective Date: 10/1/22 Cancels: N/A Page: 2 of 2

 Select your RP1210 device. Set the communication selection to J1939:Baud=Auto, Channel = 1. Select Save.



- Follow the instructions on the tool by making sure the RP1210 device is properly connected, the vehicle is powered, and the engine is not running.
- Select Start. The progress bar will show the progress of the download. Once the utility finishes the download process, the tool will display Download Successful.
- Long key cycle the truck and the fault should be resolved.

Refer to the Bendix® Wingman® Fusion™ FLR-21™ Radar Sensor Service Data Sheet, SD-61-4963, on b2bendix.com for any other issues observed with the radar sensor.







