

# Technical Bulletin

Bulletin No: TCH-001-046

Effective Date: 8/1/98

Cancels: N/A

Page: 1 of 1

## Subject: ADDITION OF FOURTH REPAIR KIT PIECE NUMBERS

The Bendix Tu-Flo 501 compressor is currently being remanufactured to fourth repair sizes. Below is a listing of all Tu-Flo 501 compressor kits and their respective repair sizes if applicable. The new piece numbers are shown in a **boldface** type, all others are for reference only.

Please update your Service Parts Catalog to reflect these changes.

<u>Kit No.</u>	<u>Description</u>	<u>Repair Size</u>
106105	Piston Ring Set	Standard
106106		.010 O.S.
106107		.020 O.S.
106108		.030 O.S.
<b>5005216</b>		<b>.040 O.S.</b>
106109	Piston & Wrist Pin Kits	Standard
106110		.010 O.S.
106111		.020 O.S.
106112		.030 O.S.
<b>5005217</b>		<b>.040 O.S.</b>
286254	Connecting Rod Insert Kit	Standard
286255	Non Thru Drive	.010 O.S.
286256		.020 O.S.
286257		.030 O.S.
<b>5005218</b>		<b>.040 O.S.</b>
287058	Connecting Rod Insert Kit	Standard
287059	Thru Drive	.010 O.S.
287060		.020 O.S.
287061		.030 O.S.
<b>5005219</b>		<b>.040 O.S.</b>
287043	Field Maintenance Kit	
279615	Unloader Kit	
101558	Gasket Kit	

