

Technical Bulletin

Bulletin No: TCH-013-012

Effective Date: 3/1/06

Cancels: N/A

Page: 1 of 1

Subject: **PC Diagnostic Software for Troubleshooting Bendix® ABS**

The latest release of ACom™ Diagnostics (version 5.2, part number 802588) is used to troubleshoot all the most recent Bendix ABS systems.

This Bulletin is to alert technicians who are troubleshooting ABS systems using the earlier Bendix® EC-15™ and EC-16™ Electronic Control Units, that from March 1, 2006, the PC diagnostic software for these two ECUs (formerly Bendix part number 5009089) will now only be available from NEXIQ Technologies, using part number 852013.

Tractors

ABS Controller

EC-15™ Electronic Control Units

EC-16™ Electronic Control Units

EC-17™ Electronic Control Units

EC-30™ Electronic Control Units

Gen 4™ and Gen 5™ ABS for Trucks, Tractors,
and Buses

EC-60™ ABS/ATC Controller (Standard & Premium)

EC-60™ ABS/ATC/ESP Controllers (Advanced Models)

Service Data Sheet

SD-13-4785 (BW1663)

SD-13-4787 (BW1726)

SD-13-4788 (BW1910)

SD-13-4815 (BW2160)

SD-13-4746 (BW2261)

SD-13-4863 (BW2428)

SD-13-4869 (BW2429)

Diagnostic Software

NEXIQ software
part number 852013

Bendix® ACom™
Diagnostics 5.2,
part number 802588.

Trailers

ABS Controller

MC-30™ Trailer ABS Electronic Control Units

A-18™ Trailer ABS (Gen 4™ and Gen 5™ ABS)

TABS-6™ Trailer ABS Module

Service Data Sheet

SD-13-4834 (BW2189)

SD-13-4757 (BW2262)

SD-13-4767 (BW2469)

Diagnostic Software

Bendix® ACom™
Diagnostics 5.2,
part number 802588.

Visit the Literature Center on www.bendix.com to download Service Data sheets or order copies, and obtain the new ABS Repair and Diagnostics DVD (BW2538).

NEXIQ Technologies can be reached at 1-800-639-6774 or visit www.NEXIQ.COM

