

# Part Number Update

Bulletin No: PNU-188




Effective Date: March 14, 2014

Cancels: PNU-188 Dated March 5, 2014

Page: 1 of 1

## Subject: Bendix® Stoplight Switch Obsolescence

Effective March 17, the following Bendix® brand components are obsolete and superseded as indicated in the table below. A complete listing — in numerical order — is also shown below for easy reference.

Bendix® Stoplight Switches				
Bendix® Designation	Image	OE Piece No.	Obsolete Service Piece No.	Service Replacement Bendix® SL-4™ Piece No.
SL-2™	--	223220	223220N	K101997
		223665	223665N	
SL-3™		226262	226262N	K101997
		226411	226411N	
		—	276963	
SL-4™		103358	103358N	K101997
		228687	228687N	K101996
		—	228688	
		—	276290	K101997
		—	283012	
—	285532	K101996		
SL-5™		102601	102601N	K101996
		107586	107586N	K101997
		286392	286392N	K101996

Piece Number Changeover - Numerical Order		
Bendix Piece No.	Bendix® Stoplight Switch	Service Replacement Piece No.
102601	SL-5™	K101996
103358	SL-4™	K101997
107586	SL-5	K101997
223220	SL-2™	K101997
223665	SL-2	K101997
226262	SL-3™	K101997
226411	SL-3	K101997
228687	SL-4	K101996
228688	SL-4	K101996
276290	SL-4	K101996
276963	SL-3	K101997
283012	SL-4	K101997
285532	SL-4	K101996
286392	SL-5	K101996

Piece Number Changeover - Numerical Order		
Bendix Piece No.	Bendix® Stoplight Switch	Service Replacement Piece No.
102601N	SL-5	K101996
103358N	SL-4	K101997
107586N	SL-5	K101997
223220N	SL-2	K101997
223665N	SL-2	K101997
226262N	SL-3	K101997
226411N	SL-3	K101997
228687N	SL-4	K101996
286392N	SL-5	K101996

