

Technical Bulletin



Bulletin No: TCH-013-028

Effective Date: 9-29-2017

Cancels: N/A

Page: 1 of 1

Subject: Bendix® ACom® Mandatory Update

Due to the recent product release of Bendix® EC-80™ brake controllers (ROM2), the Bendix® ACom® diagnostic software must be updated to version 6.14 or greater.

Bendix ACom version 6.13 and previous versions are not compatible with Bendix EC-80 brake controllers on vehicles built since **May 1, 2017**.

Features such as Hill Start Aid (HSA) and/or Bendix® Wingman® Active Cruise with Braking may be disabled if ACom diagnostic software was used to modify any of the Bendix EC-80 options (listed below) in the Change Configuration Window on a vehicle equipped with Bendix® ESP® Stability EC-80™ Electronic Control Unit (ECU) produced since May 1, 2017, or Bendix® ABS or ATC EC-80™ ECU produced since July 1, 2017.

- Retarder Engine Interface Option
- High Resolution Wheel Speed Option
- Wheel Speed Information Option
- Electronic Brake Controller Option
- Cruise Control/Wheel Speed Option
- Rail Mode Switch Option

For additional information, contact the Bendix Tech Team at 1-800-AIR-BRAKE (1-800-247-2725), Monday through Friday, 8:00 a.m. to 6:00 p.m. ET.



**Bendix® ABS
EC-80™ Controller**



**Bendix® ATC
EC-80™ Controller**

Log-on and Learn from the Best

On-line training that's available when you are –24/7/365.
Visit www.brake-school.com.

Trucking moves fast. Move faster.
Knowledge Dock™
• BLOGS • PODCASTS • VIDEOS • 24/7/365
knowledge-dock.com