

# Part Number Update

Bulletin No: PNU-164

Effective Date: October 10, 2011

Cancels: N/A

Page: 1 of 1

## Subject: Bendix® AR-1™ and AR-2™ Antilock Relay Valve Obsolescence Notice

The following antilock relay valves are reaching the end of their availability for direct service replacement. See the table below for the replacement kit numbers to use when the current stock is depleted.



FIGURE 1 - BENDIX® AR-1™ AND AR-2™ ANTILOCK RELAY VALVES (CAN BE EXTERNALLY IDENTICAL IN APPEARANCE).

Part Number	Bendix Designation	Replacement Kit	Stock Depletion Estimate
065327	AR-1™ Antilock Relay Valve	K065765	Within 30 days
065330	AR-2™ Antilock Relay Valve	K065763	During 2012
065360	AR-1™ Antilock Relay Valve	K065765	During 2012
065364	AR-2™ Antilock Relay Valve	K065764	Within 30 days
065501	AR-1™ Antilock Relay Valve	K065765	Within 30 days
800163	AR-1™ Antilock Relay Valve	K065765	Within 30 days
800179	AR-1™ Antilock Relay Valve	K065765	December, 2011
800186	AR-2™ Antilock Relay Valve	K065763	Within 30 days
800187	AR-2™ Antilock Relay Valve	K065764	Within 30 days
800297	AR-1™ Antilock Relay Valve	K065765	During 2012
800299	AR-2™ Antilock Relay Valve	K065763	Within 30 days
800387	AR-1™ Antilock Relay Valve	K065765	Within 30 days
800537	AR-1™ Antilock Relay Valve	K065767	During 2012
800605	AR-1™ Antilock Relay Valve	K065765	December, 2011
801035	AR-2™ Antilock Relay Valve	K065763	During 2012