

Part Number Update

Bulletin No: PNU-105

Effective Date: 2/1/2006

Cancels: N/A

Page: 1 of 1

Subject: **M-30 to M-32 Modulator Transition**

M-30 modulators are transitioning to M-32 modulators. The M-32 is a direct replacement for the current M-30 modulator. Some M-30 modulator part numbers will no longer be available starting in February 2006. The following tables provide a cross-reference of part numbers (both OE and Service) of the M-32 modulator direct replacement for the M-30 modulator. Please reference Technical Bulletin TCH-013-011 for additional details on direct replacement. This bulletin is being sent out for the second time, in as many months, to provide clarity for this part number update. Technical Bulletin TCH-013-011 has not been modified in any way from the original. If you have any questions on this information, please call 1-800-AIR-BRAKE.

Service Numbers

M-30 Service Part Number	Description	M-32 Service Replacement Part Number
800665	Anti-lock modulator	801481
800666	Anti-lock modulator	801479
800968	Anti-lock modulator	801481
801077	Anti-lock modulator	801481
801078	Anti-lock modulator	801583
801079	Anti-lock modulator	801583
801080	Anti-lock modulator	801457
801081	Anti-lock modulator	801457
801082	Anti-lock modulator	801456
801083	Anti-lock modulator	801456

OE Numbers

M-30 OE Part Number	Description	M-32 OE Replacement Part Number
5005894	Anti-lock modulator	5014705
5005895	Anti-lock modulator	5014704
5006625	Anti-lock modulator	5011280
5006626	Anti-lock modulator	5011278
5006658	Anti-lock modulator	5011280
5008927	Anti-lock modulator	5011280
5008951	Anti-lock modulator	5011280
5009085	Anti-lock modulator	5016334
5009086	Anti-lock modulator	5016334
5009304	Anti-lock modulator	5011280
5009305	Anti-lock modulator	5012961
5009306	Anti-lock modulator	5012961
5009308	Anti-lock modulator	5016344
5009309	Anti-lock modulator	5016344

