
## OTHERS JUST CAN'T COMPETE





35%

less oil passing than the competition




\*Higher levels of oil passing may cause downstream contamination and total failure.

## Don't get burned by inferior parts. Only genuine Bendix reman BA-921 HDEP compressors are:

- Remanufactured to OE clearances and specifications
- Tested to the highest standard using proprietary test specifications
- Expertly remanufactured to outlast any competitor




## Stay on the road and out of the service bay with genuine Bendix® remanufactured compressors.



Visual representation only. Not to scale and not intended to illustrate actual clearances.

Bendix rebores the crankcase and matches the piston to maintain OE clearances each time a compressor is remanufactured.

Not maintaining the OE piston to crankcase clearances may cause a higher volume of oil passing, increasing the risk of down stream contamination and component failure.



Non-Genuine Rebuilt BA-921 HDEP Compressor

## **Built to Compete. Remanufactured to last.**

Contact your Bendix account representative to learn more about the genuine Bendix BA-921 HDEP remanufactured compressor today.



