Technical Bulletin

Bulletin No.: PRO-10-03 Effective Date: 5/15/83 Cancels: N/A Page: 1 of 1

Subject: INSTRUCTION SHEET AMENDMENT CRUISE CONTROL KIT 209893 FREIGHTLINER CAB-OVER ENGINE

The purpose of this bulletin is to emphasize the importance of the position of the two $\frac{1}{4}$ " - 20 X $\frac{3}{4}$ " cap screws referred to on Page 7, Instruction 7 and illustrated in Figure 5 of BWS-808 Kit 209893 Freightliner Cab-Over Engine.

These two bolts <u>must</u> be installed as shown, with head of bolt on the backside of the throttle lever bracket to allow for adequate clearance throughout the entire travel of the bell crank.

