

Part Number Update

Bulletin No: PNU-191



Effective Date: October 17, 2014

Cancels: N/A

Page: 1 of 1

Subject: **Bendix® Stoplight Switch Obsolescence**

Effective immediately, the following Bendix® components are obsolete and superseded as indicated in the table below.

From		To	
Obsolete Bendix® SL-5™ Bendix® Stoplight Switch		Bendix® SL-4™ Stoplight Switch Service Replacement	
Image	Service Piece No.	Service Piece No.	Image
	802173	K101996	
	104057N	K101997	
	104748N	K101997	
	286404N	K101997	
	287416N	K101996	
	287624N	K101997	

