

Technical Bulletin

Bulletin No: TCH-022-003

Effective Date: 12/5/2016

Cancels: N/A

Page: 1 of 1

Subject: IMPROVED PARTS IDENTIFICATION FOR BENDIX® RSD REPLACEMENT CAMSHAFTS

To make it easier for drum brake customers to identify the correct service replacement camshaft, Bendix is now stamping the camshaft part number on the head. This process is done in production for both 10- and 28-tooth camshafts. See *Figure 1*.

The suffix “N” on the part number denotes that this is a service new part. Part numbers ending in even numbers (e.g. K117632N) are for the left hand camshafts (rotation is counterclockwise), and those ending in odd numbers (e.g. K117633N) are for the right hand camshafts (rotation is clockwise). See *Figure 2*.

Also, to ensure the camshaft is a genuine Bendix® part, “BENDIX” is now stamped on the inside of the cam head. See *Figure 3*.




Figure 1 – S-Cam Part Number Location



Figure 2 – Left and Right Hand Camshafts



Figure 3 – Bendix Identification on Camshaft

RSD Cam kit part number K126580K must be used when servicing the RSD Cam to remain compliant with the RSD mandate. The kit consists of the following:

Description	Qty.
Flat Washer	3
Washer	2
Washer	1
Snap Ring	1
Cam Washer	1
Bronze Bushing	2
Seal	2

As always, we stand ready to address any questions or concerns you may have regarding these updates. Please contact your Bendix Representative or the Bendix Tech Team at 1-800-AIR-BRAKE (1-800-247-2725), option 2.

