

# *Technical Bulletin*

Bulletin No.: TCH-001-041    Effective Date: 1/1/95    Page: 1 of 1

Subject: **Remanufactured Coupling Drive Gear Obsolescence**

Remanufactured coupling drive gears for Cummins compressors will no longer be available after January 31, 1995. This program will be serviced by the service new gears available through the Bendix Truck Products program.

Obsoleted Part

253285 (Reman)  
253248 (Reman)

Superseding Part

AR200398 (Service New)  
AR3000174 (Service New)

Additional information on AR200398 and AR3000174 can be found in Bendix Truck Products Compressor catalog (BW1736) and Price Bulletins PRI-412 (U.S.) and PRI-412C (Canada).

