

# *Part Number Update*

Bulletin No: PNU-037

Effective Date: 10/1/00

Cancels: N/A

Page: 1 of 1

**Subject: REMANUFACTURED AD-9 CHANGE**

Bendix is eliminating the bracket kit and the harness and splicing kit from the remanufactured AD-9 dryer. There will be no change to the part number or to the price. The mounting bracket kit (107695) and the harness and splicing kit (109871) are both available as kits if needed.

Description	Part Number	Product Change
AD-9 Air Dryer RX	109685	Elimination of parts 107695 & 109871

