

Part Number Update

Bulletin No: PNU-185

Effective Date: November 21, 2013 Cancells: NA


Page: 1 of 1

Subject: Bendix® AH-4™ Air-Hydraulic Intensifier Parts Obsoleted

Effective November 21, 2013, the following Bendix® AH-4™ Air-Hydraulic Intensifier, Rotochamber and associated part numbers will be obsoleted.

Obsolete Bendix® AH-4™ Parts	Description
101217	Cover Complete
101218	Rotochamber
101219	Hydraulic Intensifier
101219N	
101338	Air-Hydraulic Intensifier
101339	Rotochamber
102085	
102086	
104976	Air-Hydraulic Intensifier
108639	Hydraulic Intensifier
286746	Master Cylinder
286746N	
286755	
286761	Hydraulic Intensifier
287069	Master Cylinder
287071	Hydraulic Intensifier
288382	Master Cylinder
288413	Hydraulic Intensifier
288463	
288653	
288657	
289091	
289091N	
289094	Rotochamber
289095	Cover Complete
289273	Air-Hydraulic Intensifier

Obsolete Bendix® AH-4™ Parts	Description
289273N	Air Hyd Intensifier
289274	Rotochamber
289383	Air-Hydraulic Intensifier
289384	
289506	Cover Complete
289516	Hydraulic Intensifier
289516N	
289517	Rotochamber
289518	Cover Complete
289829	Master Cylinder
289832	
289832N	
289833	
290681	Mounting Bracket
291952	Body
292425	Cover
292663	
292672	
293265	
299402	Hydraulic Intensifier
299403	
290908	Body
290910	
288712	Mineral Oil Reservoir
290931	Bail
292174	Cover



Bendix® AH-4™
Air-Hydraulic Intensifier
with Rotochamber

See below for maintenance kits still available.

Bendix® AH-4™ Air-Hydraulic Intensifier Master Cylinder Rebuild Kit Part Numbers	Systems Using Brake Fluid	289286
		Systems Using Mineral Oil



Reference Documents:

The Service Data Sheet for Bendix® AH-4™ Air-Hydraulic Intensifier is SD-11-1357; for the Bendix® Type 50 Rotochamber Service Data Sheet see SD-02-1336. These documents are available for download from the Bendix Document Library, or the Literature Center, at www.bendix.com.

For more information contact your Bendix Account Manager or a Bendix Service Plant at 1-800-AIR-BRAKE (1-800-247-2725).