

Part Number Update

Bulletin No: PNU-189



Effective Date: March 11, 2014

Cancels: N/A

Page: 1 of 1

Subject: Bendix® Stoplight Switch Obsolescence

Effective immediately, the following Bendix® components are obsolete and superseded as indicated in the table below. A complete listing — in numerical order — follows for easy reference.

Bendix® Double Check Valve & Stoplight Switch				
Bendix® Designation	Image	OE Piece No.	Obsolete Service Piece No.	Service Changeover Kit Piece No.
DS-1™		228050	228050N	K108140
		228520	228520N	
		—	229493	
		—	228165N	K108141
DS-2™		286452	286452N	K108142
		286453	286453N	K108143
		—	286704	
		287287	287287N	
		5010488	5010488N	

Piece Number Changeover - Numerical Order		
Bendix Piece No.	Bendix® Stoplight Switch	Service Replacement Piece No.
228050	DS-1™	K108140
228520	DS-1	K108140
229493	DS-1	K108140
286452	DS-2™	K108142
286453	DS-2	K108143
286704	DS-2	K108143
287287	DS-2	K108143
5010488	DS-2	K108143
228050N	DS-1	K108140
228165N	DS-1	K108141
228520N	DS-1	K108140
286452N	DS-2	K108142
286453N	DS-2	K108143
287287N	DS-2	K108143
5010488N	DS-2	K108143

For technical information on the Bendix® DS-1™ and DS-2™ changeover see bulletin TCH-006-005.

