

# Technical Bulletin

Bulletin No: TCH-001-023

Effective Date: 10/30/82

Cancels: NA

Page: 1 of 1

**Subject: FORD OFFSET MOUNT AND CATERPILLAR 3406  
COMPRESSORS**

Traditionally Bendix remanufactured compressors have been supplied with the necessary mounting gaskets, o-rings, etc. Two exceptions to this general practice currently exist and are noted below.

We are currently working to correct this situation and will include these components with the basic compressors in the near future. In the interim these parts must be obtained separately from the appropriate O.E. parts outlet. Please record the O.E. part numbers on the catalog pages shown.

1. The base gasket for Ford offset mount compressors is not supplied. The Ford part number for this gasket is D4TZ-2B885-A. The remanufactured basic compressors affected are:

<u>PC. NO.</u>	<u>COMPRESSOR MODEL</u>	<u>CATALOG PAGE</u>
286558	TuFlo 501	01-E-12
286561	TuFlo 501	01-E-12
286562	TuFlo 501	01-E-12

2. The crankshaft o-ring on flange mounted compressors for the Cat. 3406 engine is not supplied. The Cat. part number for this o-ring is 5H2767. The remanufactured basic compressors affected are:

<u>PC. NO.</u>	<u>COMPRESSOR MODEL</u>	<u>CATALOG PAGE</u>
285131	TuFlo 500	01-D-33
286546	TuFlo 501	01-E-13
288710	TuFlo 600	01-F-17
289349	TuFlo 700	01-K-11

