

Technical Bulletin

Bulletin No.: TCH-001-036 Effective Date: 2/1/92

Cancels: N/A

Page: 1 of 1

Subject: **Tu-Flo 550 & Tu-Flo 750 Rod & Piston Maintenance Kits**

It has been found that certain new generation compressor (Tu-Flo 550/750) applications require steel wrist pin bushings.

Two new piston and rod maintenance kits, which contain the steel bushing, have therefore been created. The kit numbers are:

Tu-Flo 550 – 108843

Tu-Flo 750 – 108842

The compressor piece numbers listed below require the new kits. Please make the necessary notations in catalog pages 01-N-1 through 17 and 01-O-1 through 21.

Tu-Flo 550 Piece Numbers

065197
107000
107506
107974
107975
108583

Tu-Flo 750 Piece Numbers

065198
107001
107507
107819
107820
108584

The bronze bushing is still available for applications other than those listed above. It is contained in the original piston and rod maintenance kits:

Tu-Flo 550 – 107968

Tu-Flo 750 – 107967

