## Part Number Update

Bulletin No: PNU-238

Effective Date: 11/11/2017

Cancels: N/A

Page: 1 of 1

The table below identifies additional service kit part numbers that are needed when servicing the Bendix<sup>®</sup> ADB22X<sup>™</sup> and ADB22X<sup>™</sup>-LT air disc brake assemblies with the tool kits shown. Please make a note of these items.

## Subject: Bendix® Tool Kit Part Numbers

| Bendix®              |                             | Additional Service<br>Kit Needed |                           |
|----------------------|-----------------------------|----------------------------------|---------------------------|
| Tool Kit<br>Part No. | Description                 | Tappet Kit<br>Part No.           | Guide Pin Kit<br>Part No. |
| K029164              | Tappet & Guide Pin Tool Kit | K092079                          | 803114                    |
| K028829              | Tappet Tool Kit             |                                  | —                         |
| K029107              | Guide Pin Tool Kit          | _                                | 803114                    |





Log-on and Learn from the Best On-line training that's available when you are -24/7/365. Visit www.brake-school.com.

As always, we stand ready to address any questions or concerns you may have regarding these updates. Please contact your Bendix Representative or the Bendix Tech Team at 1-800-AIR-BRAKE (1-800-247-2725), option 2. Thank you for your business and your continued support.

