Part Number Update



Bulletin No: PNU-235 Effective Date: 1/18/2018 Cancels: Same dated: 8/29/2017 Page: 1 of 1

Subject: Bendix® M-32™ to M-40™ Modulator Changeover - New Numbers

The Bendix® M-32™ pressure modulator valves have been replaced by the Bendix® M-40™ modulator valves. The table below shows the cross reference from M-32 modulator valves to the corresponding M-40 replacements. The Comments column specifies special fittings/ adapters that must be purchased to facilitate the installation. When replacing an M-32 modulator, it is recommended that the modulators on both sides of the axle be replaced at the same time.



| 1 | | Bendix® M-40™ | Comments |
|---------------------------------------|---|------------------------------|--|
| | Bendix [®] M-32 [™] Part No. | Service Replacement Part No. | (NPT = National Pipe Thread, PTC = Push-To-Connect, STC = Snap-To-Connect) |
| Announced in bulletin dated 8-29-2017 | 801455 | K128912OR | Needs 1/2" NPT to 1/2" PTC fitting. |
| | 801456 | K128914OR | Needs 1/2" NPT to 5/8" PTC fitting on the supply port. Needs 1/2" NPT to 1/2" STC fitting on the delivery port. |
| | 801457 | K128915OR | Needs 1/2" NPT to 1/2" STC fitting on the delivery port. |
| | 801479 | K128916OR | No special considerations. |
| | 801582 | K128914OR | Needs 1/2" NPT to 5/8" PTC fitting on the supply port. Needs 1/2" NPT to 1/2" STC fitting on the delivery port. |
| | 801583 | K128915OR | Needs 1/2" NPT to 1/2" PTC 45° fitting on the delivery port. |
| | 801584 | K128915OR | Needs 1/2" NPT to 1/2" STC fitting on the delivery port. |
| | 801585 | K128914OR | No special considerations. |
| | 802363 | K156037OR | |
| | 802888 | K079667OR | Needs 1/2" NPT to 1/2" PTC 45° fitting on the delivery port. |
| | K043395 | K128922OR | No special considerations. |
| | K050343 | K128918OR | No special considerations. |
| New Numbers | 801453 | K128924OR | No special considerations. |
| | 801481 | K079670OR | |
| | 801482 | K128912OR | |
| | 801665 | K128913OR | |
| | 801967 | K128912OR | Needs 1/2" NPT to 3/8" NPT fitting on the supply port. |
| | 802697 | K128917OR | No special considerations. |
| | K023412 | K128920OR | |
| | K024918 | K079684OR | |
| | K025277 | K128921OR | |
| | K031825 | K128926OR | |
| | K040967 | K128921OR | |
| | K042041 | K128919OR | |
| | K051348 | K128920OR | |
| | K054635 | K128920OR | |
| | K089166 | K128919OR | |
| | 801666 | K161888OR | |
| | 801736 | K161992OR | |
| | 801737 | K161960OR | |
| | 801454 | K161979OR | |

As always, we stand ready to address any questions or concerns you may have regarding these updates. Please contact your Bendix Representative or the Bendix Tech Team at 1-800-AIR-BRAKE (1-800-247-2725), option 2. Thank you for your business and your continued support.