## Part Number Update

Bulletin No: PNU-172

Effective Date: September 23, 2013 Cancels: PNU-172, June 1, 2013

Page: 1 of 1

## Subject: Bendix® FLR10™ Forward Looking Radar Sensor Service Replacements and Bracket Kits

Effective June 1, 2013, the following reman radar sensor and bracket kits were made available for Bendix® Wingman® ACB and Bendix® Wingman® Advanced™ Active Cruise with Braking systems. The original service replacement radar units are no longer available.

Vehicle Application	Original Service New Part	Order this Reman Part Number	Bracket Assembly Kits	Bracket Style
Volvo® VN Vehicles	K056476	Core Group: SG Core Class: F6	K094250	
Mack <sup>®</sup> CXU; CHU	K056479		K043222 Base Bracket; K094250 Front Bracket	
Peterbilt® 386	K056483		K055673	
Kenworth® T660 Vehicles	K056488		K063722 Side Bracket;	
Kenworth® T700 Vehicles	K056488		K063758 Front Bracket	
Peterbilt® 587	K057743		K051907 Base Bracket; K094245 Front Bracket	
Peterbilt® 579	K057745		K057492 Base Bracket; K094245 Front Bracket	
Kenworth® T680	K057747		K057493 Base Bracket; K094245 Front Bracket	
Kenworth® T800	K057749		K094251	
Universal Radar Sensor	K090770		(not applicable)	





Note: These bracket assembly images show a radar sensor installed.

