| Change from:  |  | Change to:  | and Receive:           | Required<br>Tag*   |
|---|--|---|------------------------|--|
| Non-Bendix<br>Air Dryers  | Any<br>Non-Genuine<br>(AD-9®- or<br>AD-IP®-style)<br>Air Dryers            | Genuine Bendix® Reman AD-9® or Bendix® Reman AD-IP® | Full<br>Core<br>credit |  |
| Non-Bendix<br>Cartridges  | Any<br>Non-Genuine<br>(AD-9- or<br>AD-IP-style)<br>Cartridges              | Genuine Bendix® Reman AD-9® Bendix® Reman AD-IP®    | Full<br>Core<br>credit | DEGRADE TAG  TO MODEL / DEVICE  CORE RETURN NUMBER  CUSTOMER CODE  CUSTOMER NAME                                 |
| Legacy<br>Bendix<br>Dryers  | Bendix <sup>®</sup> AD-2 <sup>®</sup><br>Air Dryer                         |   |                        | 304126 E-2015 Sende Comment Inhibit System LLC, a member of the<br>North Benne Citics - CE11 - AR Syste Research |
|   | Bendix <sup>®</sup> AD-4 <sup>™</sup><br>Air Dryer                         |   |                        | Use BW1829   |
| Bendix<br>Dryers<br>with Minor<br>Damage or<br>Co-Mingled<br>Hardware | Bendix <sup>®</sup> AD-9<br>Air Dryer                                      | Genuine Bendix® Reman AD-9® or Bendix®              | Full<br>Core           |  |
|   | Bendix <sup>®</sup> AD-IP<br>Air Dryer                                     | Reman AD-IP®  | credit                 |  |
|   | Bendix <sup>®</sup> AD-SP <sup>®</sup><br>Air Dryer                        | (09) (29) (9A) (79)                                 |                        |  |
| (Spin on<br>Cartridges)   | Any<br>Genuine<br>AD-IS <sup>®</sup> Dryer<br>with non-Bendix<br>Cartridge | Bent 9C   | Full<br>Core<br>credit | Upgrade Tag<br>Not Required  |

- Changeover Cores must be tagged "Upgrade" (use orange upgrade tag BW1829). Return with remanufactured exchange Cores. Air dryer Cores incorrectly tagged will not be eligible for credit.
- Note: Only the dryers listed above are included in the upgrade offer.