

WARNING

ALL COMPONENTS CONTAINED IN THIS KIT MUST BE USED WHEN SERVICING THE TU-FLO 550 OR TU-FLO 750 CYLINDER HEAD. FAILURE TO DO SO MAY RESULT IN COMPRESSOR FAILURE.