## Technical Bulletin

Bulletin No.: TCH-003-006

Effective Date: 8/9/76

Page: 1 of 2

Subject: QR-1 Valve

Ref: Attached sketches


Over the years, we have received complaints of noise in the QR-1 valve when it is exhausting. Engineering has come up with a good fix, which field testing has proven eliminates the noise. The fix is a small piece of polyurethane foam material cut in the shape of a cross and placed on top of the diaphragm. The insert is #292362. The part number of a QR-1 valve with the insert is piece #289042. Piece #289042 has 3/8" supply port and ¼" delivery ports. This valve #289042 has 1 psi supply and delivery differential.

The insert can be used in any QR-1 valve to eliminate the noise. The insert #292362 is placed in the center of the diaphragm on the top side or supply side of the diaphragm.


For reference see attached sketches.



## INSERT FOR QUICK RELEASE VALVE



CORNERS MAY BE ROUNDED



ATTACHMENT TO PRODUCT BULLETIN 03-6 DATED 8/9/76