

# Part Number Update

Bulletin No: PNU-208




Effective Date: April 24, 2015

Cancels: NA

Page: 1 of 1

Subject: **Bendix Announces Bendix® ABS, ATC, & ESP® EC-80™ Electronic Control Units (ECUs) for PACCAR® Vehicles**

Effective immediately, the following Remanufactured Bendix® EC-80™ family of ECUs are available for PACCAR® vehicles.

Type of ECU	Image	Bendix Part Number	OE Part Number	Order Replacement Reman Part Number	(Only for 6x2 tractors without Bendix® eTrac™ System)	Core Group	Core Class
Bendix® ABS EC-80™ Controller		K098915R000	Q27-6073-101	<b>K114398N000</b>	-	SV	E6
Bendix® ATC EC-80™ Controller		K098916R000	Q27-6073-201	<b>K114425N000</b>	<b>K114427N000</b>	SX	E8
		K098917R000	Q27-6073-202	<b>K114426N000</b>	<b>K114428N000</b>		
		K098918R000	Q27-6073-203	<b>K114401N000</b>	-		
		K098919R000	Q27-6073-204	<b>K114402N000</b>			
Bendix® ESP® EC-80™ Controller		K105094R000	Q27-6073-305	<b>K114403N000</b>	-	SW	E7
		K105095R000	Q27-6073-306	<b>K114404N000</b>			
		K105096R000	Q27-6073-307	<b>K114405N000</b>			
		K105097R000	Q27-6073-308	<b>K114406N000</b>			
<p>Note: Remanufactured Bendix® ESP® EC-80™ Controllers are made-to-order and only available through an authorized PACCAR dealer. The vehicle VIN is required in order to properly process the order. These parts cannot be stocked, direct ship only.</p>							

#### Reference Documents:

For Bendix ABS/ATC EC-80 Controllers download/order Bendix® Service Data Sheet SD-13-4983.

For Bendix ESP EC-80 Controllers download/order SD-13-4986.

**Downloads:** Go to the Document Library on [www.bendix.com](http://www.bendix.com) for Service Data Sheets.

**Printed Copies:** Literature can be ordered directly from the on-line Bendix Literature Center. To register or to access your existing account, visit [www.bendix.com](http://www.bendix.com) and click on the "Marketing Center" tab at the top of the homepage, or use the link on [www.foundationbrakes.com](http://www.foundationbrakes.com).

**Electronic and PC Troubleshooting:** The Bendix ABS, ATC & ESP EC-80 Controllers require version 6.7.2.5, or later, of the Bendix® ACom® Diagnostics Software. For free downloads go to [www.bendix.com](http://www.bendix.com) (or order BW2329 from the web site Marketing Center). When using a Bendix® Remote Diagnostic Unit (RDU™) for Bendix ABS, ATC & ESP EC-80 Controllers, use Part number K101596N001.

#### Log-on and Learn from the Best

On-line training that's available when you are —24/7/365.  
Visit [www.brake-school.com](http://www.brake-school.com).



Trademarks. The ACOM, EC-80 and ESP trademarks are licensed to or owned by Bendix Commercial Vehicle Systems LLC. Any references in this Bulletin to PACCAR, and any other company or trademark are solely for identification and cross reference purposes. The trademarks are the property of their respective companies and are not affiliated with or endorsing Bendix Commercial Vehicle Systems LLC. Bendix Commercial Vehicle Systems LLC does not represent any parts shown as products manufactured or remanufactured by the companies so named herein.

©2015 Bendix Commercial Vehicle Systems LLC, a member of the Knorr-Bremse Group • 04/15 • All Rights Reserved.