

Part Number Update

Bulletin No: PNU-214


Effective Date: July 6, 2016

Cancels: NA

Page: 1 of 1

Subject: **BENDIX® AD-RP™ AIR DRYER (SERVICE NEW) ALTERNATIVE FOR VOLVO® AND MACK® TRUCKS**

Effective immediately, select Bendix® AD-RP™ air dryers are being replaced with new Bendix AD-RP air dryers that contain a Bendix® PuraGuard® oil coalescing cartridge. This is an aftermarket-specific air dryer appropriate for use on most Volvo and Mack trucks equipped with an external purge tank.



Bendix AD-RP PG Air Dryer

Bendix AD-RP Air Dryer Service Replacement Part Number (Bendix-to-Bendix Replacement):

Old Bendix® Air Dryer Part Number	New Bendix Service Replacement Part Number	Bendix Air Dryer Description	Recommended Compressor Type
802519	802519PG	AD-RP PG 12V	Single Cylinder
K062724	K062724PG	AD-RP PG 12V DLU	Twin Cylinder

To Changeover to a Bendix AD-RP Air Dryer:

For Meritor®		For WABCO®			Select Bendix Service Replacement Part Number
Part Number	Part Number	Cartridge Type	Service Part Number	Air Dryer Description	
R955300	S432 413 024 0	Standard	S432 421 048 7	1200P-style, 12V heater and turbo cut-off valve (recommended for use with single cylinder compressors)	802159PG
R955079	S432 421 048 0	Coalescing			
N/A	S432 421 015 0	Standard	S432 421 015 7	1200UP-style, 12V heater and discharge line unloading option (recommended for use with twin cylinder compressors)	K062724PG
R955082	S432 421 033 0	Coalescing	S432 421 033 7		

Have questions? Want more information? Contact your Bendix account representative, visit us online at bendix.com, or call 1-800-AIR-BRAKE (1-800-247-2725, option 2).

Log-on and Learn from the Best
 On-line training that's available when you are –24/7/365.
 Visit www.brake-school.com.

