Part Number Update

Bulletin No: PNU-213 Effective Date: April 24, 2015 Cancels: NA Page: 1 of 1

Subject: Bendix Announces Bendix® ABS, ATC, & ESP® EC-80™ Electronic Control Units (ECUs) for Navistar® Vehicles

Effective immediately, the following Remanufactured Bendix[®] EC-80[™] family of ECUs are available for Navistar vehicles.



Type of ECU	Bendix Part Number	OE Part Number	Reman Replacement Part No. Direct Ship*	Core Group	Core Class
Bendix [®] ABS EC-80 [™] Controller without PLC	K103425R000	4045848C1	K115809N000	SV	E6
Bendix ABS EC-80 Controller	K103426R000	4045849C1	K115809N000		
Bendix [®] ATC EC-80 [™] Controller	K103427R000	4045850C1	K115811N000	SX	E8
Bendix ATC EC-80 Controller with Hill Start Assist	K103474R000	4045851C1	K115810N000		
Bendix [®] ESP [®] EC-80 [™] Controller	K103428R000	4045852C1	K119760N00	SW	E7
	K103429R000	4045853C1	K114403N000		

Note: All remanufactured Bendix[®] ESP[®] EC-80[™] Controllers are made-to-order and only available through an authorized Navistar dealer. The vehicle VIN is required in order to properly process the order.

*Bendix EC-80 Controllers cannot be stocked as they are programmed specifically for a vehicle, and so can only be ordered as direct ship items.

Reference Documents:

For Bendix® ABS/ATC EC-80™ Controllers dowload/order Bendix® Service Data Sheet SD-13-4983.

For Bendix® ESP EC-80™ Controllers download/order SD-13-4986.

Downloads: Go to the Document Library on www.bendix.com for Service Data Sheets.

Printed Copies: Literature can be ordered directly from the on-line Bendix Literature Center. To register or to access your existing account, visit www.bendix.com and click on the "Marketing Center" tab at the top of the homepage, or use the link on www.foundationbrakes.com.

Electronic and PC Troubleshooting: The Bendix ABS & ATC EC-80 Controllers require version 6.7.2.5, or later, of the Bendix® ACom® Diagnostics Software. For free downloads go to www.bendix.com (or order BW2329 from the web site Marketing Center). When using a Bendix® Remote Diagnostic Unit (RDU™) for Bendix ABS & ATC EC-80 Controllers, use Part number K101596N001.

Log-on and Learn from the Best

On-line training that's available when you are -24/7/365. Visit www.brake-school.com.



Trademarks. The ACOM, EC-80 and ESP trademarks are licensed to or owned by Bendix Commercial Vehicle Systems LLC. Any references in this Bulletin to NAVISTAR, and any other company or trademark are solely for identification and cross reference purposes. The trademarks are the property of their respective companies and are not affiliated with or endorsing Bendix Commercial Vehicle Systems LLC. Bendix Commercial Vehicle Systems LLC does not represent any parts shown as products manufactured or remanufactured by the companies so named herein.