

# Part Number Update

Bulletin No: PNU-224

Effective Date: February 16, 2016 Cancels: NA

Page: 1 of 1


Subject: **New Bendix® ADB22X™ Air Disc Brake Conventional Rotor Part Numbers**

Effective immediately, Bendix Spicer Foundation Brake LLC (Bendix) announces the following new part numbers are available for order as direct replacements for the two part numbers being obsoleted.

Obsolete Part Number	Order this Replacement Part Number
802081	K038573
802082	K038574

The new part numbers are compatible for fit and function. Please use the new part numbers for future orders.

To learn more please contact your Bendix Account Manager, visit [www.foundationbrakes.com](http://www.foundationbrakes.com), or call 1-800-AIR-BRAKE (1-800-247-2725, option 2).



**Bendix® ADB22X™ Conventional Rotors.**  
**Includes: Hex cap screws.**

## Reference Documents:

For Bendix® ADB22X™ and ADB22X-V™ Air Disc Brakes download/order Service Data Sheet SD-23-7541.

**Downloads:** Go to the Document Library on [www.foundationbrakes.com](http://www.foundationbrakes.com) or [www.bendix.com](http://www.bendix.com) for Service Data Sheets.

**Printed Copies:** Literature can be ordered directly from the on-line Bendix Literature Center. To register or to access your existing account, visit [www.foundationbrakes.com](http://www.foundationbrakes.com) and click on the "Marketing Center" tab at the top of the home page, or use the link on the [www.bendix.com](http://www.bendix.com).



## Log-on and Learn from the Best

On-line training that's available when you are —24/7/365.  
Visit [www.brake-school.com](http://www.brake-school.com).