

Part Number Update

Bulletin No: PNU-296

Initial Release Date: 5/31/24

Revision Date: N/A

Page: 1 of 1

Subject: **New SmarTire® by Bendix CVS Tire Pressure Monitoring System (TPMS) Black Series Sensor Part Numbers**

Effective May 31, 2024, the following new replacement part numbers are available for SmarTire® by Bendix CVS Tire Pressure Monitoring System (TPMS) Black Series sensors. Refer to Table 1 to identify the correct replacement part number.



Use of the incorrect sensor will lead to a sensor Diagnostic Trouble Code (DTC), resulting in data from the sensor not being received by the Bendix® Electronic Control Unit (ECU). If using a tool to learn the new sensor, the system will not accept the incorrect sensor type. However, if using Bendix® ACom® Diagnostic Software to program the ID directly into the ECU, the ID code will be accepted, but the sensor transmissions will not be recognized by the ECU; after a period of time, the system will issue a sensor DTC.

Obsolete Service New Part Number	Replacement Service New Part Number	Description
K141481	K286247	Black Series - Strap Mount Cradle AM - TPMS Sensor Transmitter
K141483	K286250	Black Series - Gold Service Replacement Strap Mount Cradle AM
K141491	K286248	Black Series - Kit with Strap 22.5-in. AM
K141493	K286249	Black Series - Kit with Strap 24.5-in. AM
K141495	K286251	Black Series - Gold Service Replacement Kit with Strap 22.5-in. AM
K141497	K286252	Black Series - Gold Service Replacement Kit with Strap 24.5-in. AM

Table 1 - Obsolete and Replacement Service New Part Numbers

