

Technical Bulletin

Bulletin No: TCH-002-004

Effective Date: 3/20/97

Cancels: NA

Page: 1 of 1

Subject: DD-3 SAFETY ACTUATOR LUBRICATION

This Bulletin is to advise that DD-3 Safety Actuator piece numbers 287475 and 287479 may have been manufactured without the lubrication needed for proper operation. If you have a suspect DD-3 Safety Actuator grease the unit with Lubriplate "Aero" lubricant BW-651-M or equivalent. The lubrication port is located on the circumference of the non-pressure plate. The actuator is properly lubricated when grease seeps out of the grease relief port located on the bottom of the actuator.

The following is a listing of piece numbers and their corresponding date codes (serial numbers) for actuators that are suspect. The date code is stamped into a metal tag secured to the emergency clamp of the actuator.

PIECE NUMBER	DATE CODES	PIECE NUMBER	DATE CODES
287475	A2497N	287479	A2597N
	B1797N		B2097N
	B1897N		B2297N
	B2197N		B2497N
	E2496N		E2496N
	F2696N		F2696N
	J2596N		H0596N
			H0696N
			H0996N
			H1396N
			H1496N
			J2596N

