
## Technical Bulletin

Bulletin No: TCH-001-043 Effective Date: 3/20/97 Cancels: N/A Page: 1 of 1

## Subject: CYLINDER HEAD GASKET FOR THE TU-FLO 550/750 AIR COMPRESSORS

A design change to the cylinder head gasket for the Tu-Flo 550/750 compressors has resulted in a gasket orientation change. When installing the cylinder head gasket the beaded side of the gasket must face the compressor crankcase when assembled.

## Bead on one side



Cylinder Head Gasket

