

# Part Number Update

Bulletin No: PNU-262


Effective Date: 10/29/2020

Cancels: N/A

Page: 1 of 1

**Subject: New Bendix® Service Parts and Kits - Kenworth® Tractors Only**

Effective immediately, Bendix is providing the following wear-sensing service parts and kits for the Bendix® ADB22X® air disc brake assemblies. This part number update is not applicable to Bendix® ADB22X®-LT air disc brake assemblies.



Description	Part Number	Sensor	Cable to Electrical Supply	Cable Protection Plate	Mounting Pin	Bendix® Components Included in Kit
Wear-Sensing Pad Kit (axle set) - Kenworth Tractors Only	K162217	✓	–	✓	✓	BX276™ Genuine OE Pad Kit
	K162218	✓	–	✓	✓	BX283™ High Duty Cycle Pad Kit
Wear-Sensing Supply Line	K163396	–	✓	–	–	Supply Line 1.5 Meter, In-Pad Wear-Sensing
Wear-Sensing Electronic Control Unit (ECU)	K162789	–	–	–	–	Wear-Sensing ECU, 250K Baud Rate, In-Pad Wear-Sensing, with Velcro
	K162791	–	–	–	–	Wear-Sensing ECU, 500K Baud Rate, In-Pad Wear-Sensing, with Velcro

**NOTE:** For information related to the part number update for Bendix ADB22X-LT air disc brake assemblies, refer to PNU-268.

