

Part Number Update

Bulletin No: PNU-268


Effective Date: 10/29/2020

Cancels: N/A

Page: 1 of 1

Subject: **New Bendix® Service Parts and Kits - Tractor/Trailer**

Effective immediately, Bendix is providing the following wear-sensing service parts and kits for the Bendix® ADB22X® and Bendix® ADB22X®- LT air disc brake assemblies.



Description	Part Number	Sensor	Cable to Electrical Supply	Cable Protection Plate	Mounting Pin	Bendix® Components Included in Kit
Wear-Sensing Pad Kit (axle set) - Tractor/Trailer	K196276	✓	–	✓	–	BX276™ Genuine OE Pad Kit
	K196283	✓	–	✓	–	BX283™ High Duty Cycle Pad Kit
Wear-Sensing Supply Line	K192257	–	✓	–	–	Supply Line 1.5 Meter, In-Pad Wear-Sensing
	K192258	–	✓	–	–	Supply Line 1.0 Meter, In-Pad Wear-Sensing
	K193988	–	✓	–	–	Supply Line 0.75 Meter, In-Pad Wear-Sensing
Wear-Sensing Electronic Control Unit (ECU)	K162789	–	–	–	–	Wear-Sensing ECU, 250K Baud Rate, In-Pad Wear-Sensing, with Velcro
	K162791	–	–	–	–	Wear-Sensing ECU, 500K Baud Rate, In-Pad Wear-Sensing, with Velcro

NOTE: For information related to the part number update solely for Bendix ADB22X air disc brake assemblies (not including Bendix ADB22X-LT air disc brake assemblies), refer to PNU-262.

