

Part Number Update

Bulletin No: PNU-205


Effective Date: January 30, 2015

Cancels: NA


Page: 1 of 1

Subject: **New Diagnostic Harnesses for Bendix® TABS-6™ Premium and Advanced Trailer ABS Systems**

Bendix announces two new diagnostic harness part numbers:

Obsolete OE Harness Part Number	Obsolete Aftermarket Harness Part Number	Harness Length (inches)	New OE Part Number	Order New Aftermarket Part Number	Comments
5007833	800790	120	K044764	K044766	 <p>9-Pin Diagnostic Connector</p>
5009193	801038	72	K044765	K044767	

Bendix announces a new diagnostic harness bracket part number compatible with the new harnesses above:

Obsolete Bracket Part Number OE	Obsolete Bracket Part Number Aftermarket	New OE Part Number	Order New Aftermarket Part Number	Comments
5013359	802021	K109022	K109023	

Log-on and Learn from the Best

On-line training that's available when you are –24/7/365.
Visit www.brake-school.com.

