## Part Number Update

Bulletin No: PNU-211

Effective Date: April 24, 2015

Cancels: NA

Page: 1 of 1

## Subject: Bendix Announces Bendix<sup>®</sup> ABS, ATC, & ESP<sup>®</sup> EC-80<sup>™</sup> Electronic Control Units (ECUs) for Mack<sup>®</sup> Vehicles

Effective immediately, the following Remanufactured Bendix® EC-80<sup>™</sup> family of ECUs are available for Mack vehicles.

Type of ECU	Image	Bendix Part Number	OE Part Number	Order Replacement Reman Part Number	Core Group	Core Class
Bendix <sup>®</sup> ABS EC-80™ Controller	Condition Conditional Conditio	K105299R000	22362086	K115125N000	SV	E6
		K105300R000	22362088	K115125N000	SV	E6
Bendix® ATC EC-80™ Controller		K105302R000	22362261	K115126N000	SX	E8
Bendix <sup>®</sup> ESP <sup>®</sup> EC-80™ Controller	BUTTLE ALCOLUMN AND ALCOLUMN	K105303R000	22362264	K115127N000	SW	E7
	Note: Remanufactured Bendix <sup>®</sup> ESP <sup>®</sup> EC-80 <sup>™</sup> Controllers are made-to-order and only available through an authorized Mack dealer. The vehicle VIN is required in order to properly process the order.					

## **Reference Documents:**


For Bendix ABS/ATC EC-80 Controllers dowload/order Bendix® Service Data Sheet SD-13-4983.

For Bendix ESP EC-80 Controllers download/order SD-13-4986.

Downloads: Go to the Document Library on www.bendix.com for Service Data Sheets.

Printed Copies: Literature can be ordered directly from the on-line Bendix Literature Center. To register or to access your existing account, visit www.bendix.com and click on the "Visit the Bendix Marketing Center" icon on the homepage, or use the link on www.foundationbrakes.com.

**Electronic and PC Troubleshooting:** The Bendix ABS, ATC & ESP EC-80 Controllers require version 6.7.2.5, or later, of the Bendix<sup>®</sup> ACom<sup>®</sup> Diagnostics Software. For free downloads go to www.bendix.com (or order BW2329 from the web site Marketing Center). When using a Bendix<sup>®</sup> Remote Diagnostic Unit (RDU<sup>™</sup>) for Bendix ABS, ATC & ESP EC-80 Controllers, use Part number K101596N001.



training that's available when you are -24/7/365 Visit www.brake-school.com.



Trademarks. The ACOM, EC-80 and ESP trademarks are licensed to or owned by Bendix Commercial Vehicle Systems LLC. Any references in this Bulletin to MACK, and any other company or trademark are solely for identification and cross reference purposes. The trademarks are the property of their respective companies and are not affiliated with or endorsing Bendix Commercial Vehicle Systems LLC. Bendix Commercial Vehicle Systems LLC does not represent any parts shown as products manufactured or remanufactured by the companies so named herein.

©2015 Bendix Commercial Vehicle Systems LLC, a member of the Knorr-Bremse Group • 04/15 • All Rights Reserved.