

# Part Number Update

Bulletin No: PNU-278

Effective Date: 12/15/2021

Cancels: N/A

Page: 1 of 1

## Subject: New Reman Shoes with No Core Outright Program

Effective January 1, 2022, Bendix is pleased to announce an Outright Coreless Drum Brake Reman Shoe program for all 4515Q FMSI (Friction Materials Standards Institute) Brake Shoe kits. Customers will not pay a core charge for these select part numbers, and may choose from two friction offerings: Bendix® Basic and Bendix® Advanced with 20K and 23K options. This new program will be available for the following part numbers:

For more information about the program, contact your account manager.



Eligible Brake Shoe Kits for Outright Program	
Brake Shoe Kit Part Number	Description
ORKT4515QBA200	Bendix® Advanced 20K Friction
ORKT4515QBA201	Bendix Advanced 20K Friction
ORKT4515QBA230	Bendix Advanced 23K Friction
ORKT4515QBA231	Bendix Advanced 23K Friction
ORKT4515QBB200	Bendix® Basic 20K Friction
ORKT4515QBB230	Bendix Basic 23K Friction

**Knowledge Dock™**  
BLOGS • PODCASTS • VIDEOS  
24/7/365  
Visit [knowledge-dock.com](http://knowledge-dock.com)

Search for Bendix products  
quickly and easily at  
**B2Bendix.com**,  
our new e-commerce tool.

**Log on and learn from the best.**  
Online training that's available  
when you are – 24/7/365.  
Visit [brake-school.com](http://brake-school.com)

