

# Part Number Update

Bulletin No: PNU-203


Effective Date: April 16, 2015

Cancels: NA

Page: 1 of 1

## Subject: BENDIX® SC-3™ CHECK VALVE OBSOLESCENCE

Bendix Commercial Vehicle Systems (Bendix) announces the following changes to the Bendix® SC-3™ check valve offering. Please make a note of these updates.



Typical Bendix® SC-3™ Check Valves

Obsolete Part Number	Direct Replacement Part Number	New Service Replacement Part Number
800376	K112234	K112234
800457	K112235	K112235
5003991	K112210	K112234
5003992	K112209	K112234
5003994	K112208	K112234
5010819	K112211	K112235
5013665	K096210	K101849*
—	K101849	K101849*
K022855	K113996	K114066
K022856	K114066	K114066

\*Check valve is manufactured from a composite material.

If you have any questions, please contact Bendix Commercial Vehicle Systems at [www.bendix.com](http://www.bendix.com) or 1-800-AIR-BRAKE (1-800-247-2725, option 2).

### Log-on and Learn from the Best

On-line training that's available when you are —24/7/365.  
Visit [www.brake-school.com](http://www.brake-school.com).

