

# Some Parts Just Can't Take The Heat

## The test results are in...

Test	Knock-off Pass/Fail	Bendix Pass/Fail
Manufacturing Quality	✗	✓
Air Leakage	✗	✓
Operating Durability	✗	✓
Drying Capacity	✗	✓
High Temperature Durability	✗	✓
Desiccant Oil Fouling	✗	✓
Vibration Resistance	✗	✓
Cold Temperature Operation	✓	✓
Freeze-up Resistance	✓	✓
High Pressure Leak/Burst	✓	✓
Paint Adhesion	✓	✓

Make sure you're getting the real thing. Look for the "Genuine Bendix".



## Take a closer look.

Knock-off Purge Valve After High Temperature Durability Test



The knock-off's purge valve fell out of the dryer prior to completing the test.

The purge valve assembly bolt became loose and backed out during testing, causing a massive air leak which resulted in depletion of the air supply in a matter of minutes. The knock-off failed after only 30% of the test was completed.

**Why Put Your Vehicle At Risk?  
Demand The Best. Demand Genuine Bendix.**

